

# JAGtechnic Ltd

7, Harvington Business Park, 54 Brampton Road, Eastbourne, East Sussex

PHONE: 0333 666 1950 FAX: 0333 666 1955

WEB: [www.jagtechnic.co.uk](http://www.jagtechnic.co.uk) EMAIL: [info@jagtechnic.co.uk](mailto:info@jagtechnic.co.uk)

COMPANY No: 8536596 VAT No: 171 2648 18



Mr Adrian Beal  
Flat 4 2 Chatsworth Gardens  
King Edwards Parade  
Eastbourne  
East Sussex  
BN207JP  
07956669667

## INVOICE

Invoice No. **11141**  
Account No. **4BEA002**  
Order Ref.  
Invoice Date. **12/06/2015**  
Payment Method. **Pending**  
Date of Work. **12/06/2015**

Registration	Make & Model	Chassis Number	Engine CC	Mileage
GGB178N	JAGUAR E-TYPE OPEN	1S2484BW	5343	79836

### **WE ARE MOVING!**

**JAGtechnic will be moving into New state of the art premises in August 2015. The New premises can be found at 11&12 White Knight Business Park, Hammonds Drive, Eastbourne. BN23 6RW. Please come along to our Grand Opening Night on 21st September at 7.30pm**

<b>NET SUB TOTAL</b>	<b>344.42</b>
VAT at 20%	68.88
<b>TOTAL</b>	<b>413.30</b>

Ownership of Goods - Items detailed upon this invoice remain the property of JAGtechnic Ltd until full and cleared payment has been received.

JAGtechnic Ltd Registered Office: 7, Harvington Business Park, 54 Brampton Road, Eastbourne, East Sussex. BN22 9BN

# JAGtechnic Ltd

7, Harvington Business Park, 54 Brampton Road, Eastbourne, East Sussex

PHONE: 0333 666 1950 FAX: 0333 666 1955

WEB: [www.jagtechnic.co.uk](http://www.jagtechnic.co.uk) EMAIL: [info@jagtechnic.co.uk](mailto:info@jagtechnic.co.uk)

COMPANY No: 8536596 VAT No: 171 2648 18



Mr Adrian Beal  
Flat 4 2 Chatsworth Gardens  
King Edwards Parade  
Eastbourne  
East Sussex  
BN207JP  
07956669667

## INVOICE

Invoice No. **11141**  
Account No. 4BEA002  
Order Ref.  
Invoice Date. 12/06/2015  
Payment Method. Pending  
Date of Work. 12/06/2015

Registration	Make & Model	Chassis Number	Engine CC	Mileage
GGB178N	JAGUAR E-TYPE OPEN	1S2484BW	5343	79836

Both Manifold To Front Pipes Blowing  
All Lower Coolant Hoses Starting To Perish  
Engine/Gearbox Oil Leaks  
Antifreeze Needs Strengthening  
Ignition Switch Falls Out.  
Intermittent Non Start  
Poor Starting When Cold Intermittently  
Brake Fluid Has More Than 4% Water Content  
Noise From Torque Converter/Gearbox Area  
RH Front Upper Ball Joint Has Play (May Improve When Greased)  
All Grease Nipples (10) Need Greasing  
Coolant Leak From Fan Temperature Switch In Bottom Hose

**Ownership of Goods** - Items detailed upon this invoice remain the property of JAGtechnic Ltd until full and cleared payment has been received.

JAGtechnic Ltd Registered Office: 7, Harvington Business Park, 54 Brampton Road, Eastbourne, East Sussex. BN22 9BN



# JAGtechnic Ltd

7, Harvington Business Park, 54 Brampton Road, Eastbourne, East Sussex

PHONE: 0333 666 1950 FAX: 0333 666 1955

WEB: www.jagtechnic.co.uk EMAIL: info@jagtechnic.co.uk

COMPANY No: 8536596 VAT No: 171 2648 18



Mr Adrian Beal  
Flat 4 2 Chatsworth Gardens  
King Edwards Parade  
Eastbourne  
East Sussex  
BN207JP  
07956669667

## INVOICE

Invoice No. **11141**  
Account No. 4BEA002  
Order Ref.  
Invoice Date. 12/06/2015  
Payment Method. Pending  
Date of Work. 12/06/2015

Registration	Make & Model	Chassis Number	Engine CC	Mileage
GGB178N	JAGUAR E-TYPE OPEN	1S2484BW	5343	79836

Labour Description	Qty	Unit Price	Price
investigate Electrical Issues	4	86.00	344.00
Of Alternator.Readings On The Low Side3.			
Battery Not Charging			
Headlamps Not Very Good			
Panel Lights Not Working			
Fans Not Working			
Wire Hanging Down By Ignition Switch			
Best Way To Balance Carbs ? Rolling Road ?			
Check For Battery Charging.Check Charge Rate At Battery And Direct Off			
Of Alternator.System Charging But Readings On The Low Side.Adjust			
Regulator And Readings Come Up.Gauge Reading OK But Ignition Light			
Stays On.Suspect Internal Fault With Alternator Rectifier.			
Headlamps Not In Very Good Condition.Stone Chipped And Insides Reflectors			
Not Very Good.RH Headlamp Loose And Different To LH-Headlamp Operation			
Comparable To Similar Car.			
Panel Lights And Rev Counter And Speedo Also Not Working.Check Fuses-OK			
Check Switch-OK Found Poor Connection To Dimmer Switch.Replace Ignition			
Warning Light Bulb As Black.Note Wiring Condition Behind Gauges Poor.			
Check Interior Fan Operation.They Are Working But Not Very Powerfully.			
Possible Fault With Blower Motor.			
Re Secure Loose Earth Wire To Rear Of instruments.			
Labour Sub Total			344.00

Parts Description	Part No	Qty	Unit Price	Price
Bulb-C15788		1	0.42	0.42
Parts Sub Total				0.42

### Important Information / Advisory Notices

Front Brake Pads Are To Big For Discs Or Discs Are To Small  
Rear Axle Leak.Supect LH Output Seal And Pinion Seal  
Rear Silencer Dented And Pipes Dented

**Ownership of Goods** - Items detailed upon this invoice remain the property of JAGtechnic Ltd until full and cleared payment has been received.

JAGtechnic Ltd Registered Office: 7, Harvington Business Park, 54 Brampton Road, Eastbourne, East Sussex. BN22 9BN