

Unit 3 Willow Farm
 Scrapers Hill
 Chiddingly
 East Sussex
 BN8 6HJ
 01825 873578
 Geoff@taylor-automotive.co.uk
 www.taylor-automotive.co.uk



INVOICE TO:

Mr Adrian Beal
 Flat 42 Chatsworth Gardens
 King Edwards Parade
 Eastbourne
 East Sussex
 BN20 7JP

INVOICE NO.
INVOICE DATE
VAT # 173 8193 84

09/07/2015

HOURLY LABOUR RATE £45.00

JOB	DESCRIPTION
	ESTIMATE
1	Remove gearbox & investigate noise, refit gearbox. - 20hrs
2	Remove bonnet & radiator to gain access to alternator, change alternator for modern unit. - 10hrs
3	Replace all engine coolant hoses & clips (involves removing inlet manifold) - 8 hrs
4	Check all carburettor float levels & rebuild with new gaskets. - 4hrs

#	DESCRIPTION	QUANTITY	UNIT PRICE	SUB TOTAL
1	Black silicone hose set	1.00	£ 250.00	£ 250.00
2	Stainless steel hose clip set	1.00	£ 50.00	£ 50.00
3	Antifreeze	1.00	£ 20.00	£ 20.00
4	Alternator upgrade kit	1.00	£ 290.00	£ 290.00
5	Inlet manifold gasket	12.00	£ 1.78	£ 21.36
6	Induction housing gasket	4.00	£ 3.33	£ 13.32
7	Water manifold gasket	4.00	£ 1.74	£ 6.96
8	SU HIF44 carburettor service kit	1.00	£ 86.50	£ 86.50
9	Automatic gearbox & torque converter reconditioning	1.00	£ 1,000.00	£ 1,000.00
				£ -
				£ -
				£ -
				£ -

PARTS SUB TOTAL	£ 1,738.14
TOTAL LABOUR HOURS	42.00
LABOUR SUB TOTAL	£ 1,890.00
VAT RATE	20%
VAT AMOUNT	£ 725.63
TOTAL	£ 4,353.77

PAYMENT TERMS 14 DAYS

CHEQUES PAYABLE TO:
 TAYLOR AUTOMOTIVE ENGINEERING
DIRECT PAYMENT
 NAT WEST
 SORT CODE 60-24-77
 ACCOUNT NUMBER 18257445