

Unit 3 Willow Farm
 Scrapers Hill
 Chiddingly
 East Sussex
 BN8 6HJ
 01825 873578
 Geoff@taylor-automotive.co.uk
 www.taylor-automotive.co.uk



INVOICE TO:

Mr Adrian Beal
 Flat 42 Chatsworth Gardens
 King Edwards Parade
 Eastbourne
 East Sussex
 BN20 7JP

INVOICE NO. 286
INVOICE DATE 23/07/2015
VAT # 173 8193 84

HOURLY LABOUR RATE £45.00

| JOB | DESCRIPTION |
|-----|--|
| 1 | Correct intermittent non starting - faulty relay |
| 2 | Investigate poor starting when cold - choke not functioning correctly replace cables and adjust. |
| 3 | Replace front upper ball joints |
| 4 | Investigate poor fuel economy - tune engine |
| 5 | Replace perished servo and distributor vacuum hoses |
| 6 | Replace crushed rear brake pipe and bleed system |
| 7 | Replace perished air inlet rubber boots |
| 8 | Investigate and correct excessive steering column play |
| 9 | Install bolts in passenger side engine mount |
| 10 | Replace spark plugs |
| 11 | Repair handbrake knob |
| 12 | Service all grease points |
| 13 | Remove bonnet & radiator |
| 14 | Remove Butec alternator and install modern alternative |
| 15 | Replace all engine coolant hoses (involves removing inlet manifold) |
| 16 | Replace all carburettor needle valves |
| 17 | Reset float levels |
| 18 | Rebuild carburettor with new seals |
| 19 | Tune engine |
| 20 | Test drive |
| 21 | Valet |

Paid by Internet 24/7/15 £4832.28 TOTAL.

| | |
|---------------------------|-------------------|
| TOTAL LABOUR HOURS | 67.00 |
| SUB TOTAL | £ 3,015.00 |
| VAT RATE | 20% |
| VAT AMOUNT | £ 603.00 |
| TOTAL | £ 3,618.00 |

PAYMENT TERMS 14 DAYS

CHEQUES PAYABLE TO:
 TAYLOR AUTOMOTIVE ENGINEERING
DIRECT PAYMENT
 NAT WEST
 SORT CODE 60-24-77
 ACCOUNT NUMBER 18257445

