

JUST HISTORIC CARS

...reviving motoring history

Mr Adrian Beal
 Flat 4, 2 Chatsworth Gardens
 King Edwards Parade
 Eastbourne
 East Sussex
 BN20 7JP

Invoice

1558

Invoice Date: 12/06/2019
 Account No: BEA002
 Order Ref:
 Date of Work: 30/04/2019
 Payment Date: Unpaid
 Payment Method:

Registration	Make	Model	Colour	Mileage
GGB 178N	Jaguar	E Type	Yellow	

Fitted new ignition switch to steering column lock, which also required minor mods. to the wiring to match/work.
 Investigated ongoing coolant leak from bottom hose area and trace to weeping otter switch, drain down coolant and fit new otter switch, refill and top up coolant.
 Replace rear exhaust mounting rubber and make up new mounting strap to improve fit (old strap oversize).

Labour	Qty	Unit	D	Sub Total
Ign switch	1.5	49.00		73.50
Otter switch	1	49.00		49.00
Exhaust mount	.75	49.00		36.75

Parts	Qty	Unit	D	Sub Total
Switch("otter")-rad.fan E.S.1/2/3 (EA.)	1	36.98		36.98
Mounting(rubber)-exhaust(tailpipe) E.S.3 (EA.)	1	2.87		2.87
carriage(spl.o/n)@cost-jag parts to JHC	1	8.00		8.00
Consumables inc. coolant, EPA costs, fasteners etc	1	4.25		4.25

For payment by BACS
 Natwest Bank account no: 78491177
 Sort code: 51-70-12
 Just Historic Cars Ltd

Labour	159.25
Parts	52.10
SubTotal	211.35
VAT (20%)	42.27
Total	253.62
Balance	253.62