




V12 Engine health sheet.

Date	20/02/2023	Technician	JB
Vehicle	Jaguar E-type V12 S3 - GGB 178N		
Mileage	850125		

Cylinder 1B		Engine temp: Hot /Cold	Cylinder 1A	
Compression:	110 PSI		Compression:	110 PSI
Leakage:	N/A	Front 	Leakage:	N/A
Location:			Location:	
Cylinder 2B			Cylinder 2A	
Compression:	120 PSI		Compression:	115 PSI
Leakage:	N/A		Leakage:	N/A
Location:			Location:	
Cylinder 3B			Cylinder 3A	
Compression:	110 PSI		Compression:	110 PSI
Leakage:	N/A		Leakage:	N/A
Location:			Location:	
Cylinder 4B			Cylinder 4A	
Compression:	110 PSI		Compression:	105 PSI
Leakage:	N/A	Leakage:	N/A	
Location:		Location:		
Cylinder 5B		Cylinder 5A		
Compression:	115 PSI	Compression:	110 PSI	
Leakage:	N/A	Leakage:	N/A	
Location:		Location:		
Cylinder 6B		Cylinder 6A		
Compression:	115 PSI	Compression:	110 PSI	
Leakage:	N/A	Leakage:	N/A	
Location:		Location:		

Firing order
1A-6B-5A-2B-3A-4B-6A-1B-2A-5B-4A-3B

Oil level:	To the max	Spark plug condition:	New
Oil condition:	Clean		
Coolant level:	Topped up		
Coolant condition:	Clear		

Notes:

The results of the compression test do not indicate any issues with the condition of the engine and are in line with what we would expect to find on an engine with similar mileage.



